



7501 East Brundage Lane
Bakersfield, Ca 93307

Office: 661-325-0855
Fax: 661-325-0888

Popcorn Machine

1. Turn all switches to "on".
2. (On first batch only) let kettle heat about 4 minutes.
3. Add oil and popcorn package.
4. Dump when popcorn is about 99% completed.
5. Repeat steps 3 and 4. Always pop at least 4-5 batches each time for best results.
6. (On final batch only) turn the kettle heat switch to "off" as soon as corn starts popping rapidly

WARNING: KEEP KETTLE SWITCH IN "OFF" POSITION WHEN NOT POPPING CORN.

KEEP DOORS OPEN WHEN POPPING. KEEP DOORS CLOSED WHEN NOT POPPING.